Name	A. Rabe H (Please Watchman	e M.K	1Lct	kin	Date	8-23	-(6	Page		of
	(Please Watchman	Print) A. Raho Ho	Mi	ALC	hin		WO #		4724	<i>U</i>
()	_	Marene							(/) {	
ins	spected From_	Cold Spri	ng			То	Cam	der		
	Exception Cha				Switch	Co	des	Statue	Repair	W. O.
item	From	То			No.	Comp.	Defect	S/Y/R	Y/N	#
1.			, n	79 941'	100 100					
2. 3.										
4,										
5.										
6.				1					 -	
7.		(4)								
8. 9.										
10.										
11.										
12.										
Item					Comm	ents	Herries Anni			W
	. 10	10 New 1	De fe	c 4	not	ed in	Are	a		
\										
										7 11
Vere sw	vitches in the area	a Inspected?		Yes_			No_			
s this a	Special Inspectio	n?		Yes_			No_			
									00	DY
Reason	for Special Inspe	ction?						(Col	711
1	1101-	//			1	D	9.		,	1
(his	2 Roberte	5		H	CHAN 1	lowe			8/24	1/6
Trac	ck Inspectors Si	gnature	S	Super	lsory Ce	tification		-	Da	te



Work Order Details (Tr)

Org ID:

MTA

Site:

LTRAIL

WO # 2546442

TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD

TRACK INSPECTION NO NEW DEFECTS NOTED IN AREA.

Alias:

Location:

License:

CHAIN_MARKER(LT Rail Chain Markers Status:

Asset:

Year:

Manufacturer:

Type:

Serial Number: Service Address:

1155 344 West North Ave, Baltimore MD

Meters:

Description

Unit of Measure

Last Reading Date

Mileage Meter:

Last Reading

CI:

Sched Star	t:
Sched Finisl	1:
Target Star	: 8/25/16
Target Finish	: 8/25/16
Actual Star	: 8/23/16
Actual Finish	: 8/24/16
Report Date	: 8/20/16
Reported By	: MTACRON
Requestor o	

Site:	LTRAIL
Priority:	1
Work Type:	РМ
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-####-05270- #############-0901-######- ########-000-30-00
Warranty Situation Present?	N
PM Num:	48480

Job Plan:	2960
Job Desc:	TEAM ONE - SECT 5 - LINT/CROM/ BWI CM 355S/488S & CROMYARD
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD		

plustwoprint.rptdesign

Mar 27, 2018, 3:15 PM

Page 2

/



Work Order Details (Tr)

Org ID:

MTA

Site:

LTRAIL

WO # 2546442

TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD

TRACK INSPECTION NO NEW DEFECTS NOTED IN AREA.

		Skill				Reason for	Work	Part	Contract	Regular	Premiun	Line
Task ID	Craft	Level	Labor	Component	Position	Repair	Accomplished	Failure Warranty	Num	Hours	Hours	Cost
Α	REPAIR	Α	RABETT					N		08:00	00:00	217.36
Α	REPAIR	М	IALCHIN				10	N		00:00	08:00	315.48
										Total Actu	al Labor:	532.84



Work Order Details (Tr)

Org ID:

MTA

Site:

: LTRAIL

WO # 2546442

TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD

TRACK INSPECTION NO NEW DEFECTS NOTED IN AREA.

10 ESTABLISH ON TRACK SAFETY PER CLOSE RPW GUIDELINES 20 INSPECT TRACK PER BALT LR CLOSE STANDARD PROCEDURES	Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty
20 INSPECT TRACK PER BALT LR CLOSE STANDARD PROCEDURES		RPW GUIDELINES							1
		INSPECT TRACK PER BALT LR							7

I KAUN INSPECTION REPORT

Name	A.Rabett	e M. Ac	chin	Date	8-24-	16	Page		of
	A.RabeH (Pleas Watchman	e Print) <u>A Rabetle</u>	M. AL.	chin		. WO#	25	4644	2
N 7.1	spected From				То				
	Exception Cha	in Marker No			Co	des	Status	Repair	W. O.
Item	From	То	No. E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.				-					
3.									
4.									
5.									
6.									
7.									
8.									
9.									
10.									
11.									
12.		-							
<u>item</u>		Wew O		Comr	nents				-
<u>)</u>				-					•
Were sy	vitches in the are	ea inspected?	Yes			. No			
s this a	Special Inspecti	on?	Yes			No		CC	PY
(h	L. La GA		Suba	Tunuc J	Rem rtification			8/25	-/16 ate



Work Order Details (Tr)

Org ID:

MTA

Site:

LTRAIL

WO # 2546439

TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S

- 1) Trk 1 CM 340+90 -341+10 running rail pumping and has a dip in it , surfacing required.
- 2) Trks-1 & 2 CM 307 +29 4 TIES PUMPING ON BOTH TRACKS.
- 3) Trks 1 & 2 CM 302 +00 North Linthicum station running rails on the north and south ends showing areas of corrosion .
- 4)Ttrk 1 CM 279+60 utility trailer is fouling the track ,trailer is 5' 3" from end of the tie 6' 9 " from running rail .
- 5) SW 30 -1 micro fractures in the straight switch point.

Track inspection complete.

Haon	mopostion complete.				
		Location:	CHAIN_MARKER	LT Rail Ch Markers	ain Status:
	Year:	Manufacture	r:		Type:
		License:			
1155	344 West North Ave, Baltimore MD				
	Description U	Init of Measure La	ast Reading Date	Last Read	ling
		Milea	ge Meter:		
	Site	: LTRAIL		Job Plan:	2959
	Priority	: 1		Job Desc:	
		Year: 1155 344 West North Ave, Baltimore MD Description L	Year: Manufacturer License: 1155 344 West North Ave, Baltimore MD Description Unit of Measure La	Location: CHAIN_MARKERS Year: Manufacturer: License: 1155 344 West North Ave, Baltimore MD Description Unit of Measure Last Reading Date Mileage Meter: Site: LTRAIL	Location: CHAIN_MARKER: LT Rail Ch Markers Year: Manufacturer: License: 1155 344 West North Ave, Baltimore MD Description Unit of Measure Last Reading Date Last Read Mileage Meter: Site: LTRAIL Job Plan:

plustwoprint.rptdesign

Mar 27, 2018, 3:14 PM

Page 2



Work Order Details (Tr)

Org ID:

MTA

Site:

LTRAIL

Target Sta	art: 8/25/16	
Target Finis	sh: 8/25/16	
Actual Sta	rt: 8/24/16	
Actual Finis	sh: 8/24/16	
Report Da	te: 8/20/16	
Reported E	By: MTACRON	
Requestor Wo		

Work Type:	РМ
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-####-05270- #############-0901-#######- ########-000-30-00
Warranty Situation Present?	N
PM Num:	48479

	TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S
Supervisor:	
Lead:	JREAVE\$3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

ecification		ASSESSMENT OF THE PARTY OF THE	Resident of the last	Blanks all 1
Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S		



Work Order Details (Tr)

Org ID:

MTA

Site:

LTRAIL

WO # 2546439

TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S

- 1) Trk 1 CM 340+90 -341+10 running rail pumping and has a dip in it, surfacing required.
- 2) Trks-1 & 2 CM 307 +29 4 TIES PUMPING ON BOTH TRACKS.
- 3) Trks 1 & 2 CM 302 +00 North Linthicum station running rails on the north and south ends showing areas of corrosion .
- 4)Ttrk 1 CM 279+60 utility trailer is fouling the track ,trailer is 5' 3" from end of the tie 6' 9 " from running rail .
- 5) SW 30 -1 micro fractures in the straight switch point.

Track inspection complete.

		Skill				Reason for	Work	Part	Contract	Regular	Premiun	Line
Task ID	Craft	Level	Labor	Component	Position	Repair	Accomplished	Failure Warranty	Num	Hours	Hours	Cost
20 AI	REPAIR	R	NELSON				10	N		08:00	00:00	210.32
20 AI	REPAIR	N	1POLLAF				10	N		08:00	00:00	210.32
									7	Total Actu	al Labor:	420.64



Work Order Details (Tr)

Org ID:

MTA

Site:

LTRAIL

WO # 2546439

TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S

- 1) Trk 1 CM 340+90 -341+10 running rail pumping and has a dip in it, surfacing required.
- 2) Trks-1 & 2 CM 307 +29 4 TIES PUMPING ON BOTH TRACKS.
- 3) Trks 1 & 2 CM 302 +00 North Linthicum station running rails on the north and south ends showing areas of corrosion .
- 4)Ttrk 1 CM 279+60 utility trailer is fouling the track ,trailer is 5' 3" from end of the tie 6' 9 " from running rail .
- 5) SW 30 -1 micro fractures in the straight switch point.

Track inspection complete.

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						1



Org ID:

Work Order Details (Tr)

Site: LTRAIL

MTA

Date Completed

Completed By

Supervisor

I RAUN INSPECTION REPURT

Name	BIL	a 1d	-		Date	8-29	1-2011	Page	1	of /
	(Plėase Watchman_	Print)	.50	7					4643	
ín	spected From_	Lintheo)ln		Artis as a second	То	Cam			
	Exception Cha	in Marker No	Track	Rall	Switch	Co	des	Status	Repair	W. O.
Item	From	То		E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.	340490	341480		7. m		R 301	332	Y	1/	
2.	302		14.2			18301	306	9	N.	
3.	279+60					m309	348	9	N	
4.					301	5304	301	7	U	
5. 6.										
7.										
8.	-			\vdash						
9.										
10.										
11.										
12.										
Item					Comr	nents				
	area p.	umping,	a Nd	has			A Property			
2	running	inils d	orco	din	3 a	t the K	hoth the	ال المال	المكال (مالا	16
3	Utility	tailer 1	Foul	ing	Truc	Kits	it 513'	From	the t	io.
	6'9" Fro			<u>, </u>						
4	Mora Fr	extures.	SIR	19/	7.5	witch	PRINT		,	
			1,7	Trá	ckin	cpoctio	N COM	glo	6	
						V				
Were sv	vitches in the area	a inspected?		Yes_			No_		_	
ls this a	Special Inspection	n?		Yes_			No_			
Reason	for Specjal Inspe	gtion? //_							C(
11	Wall K	Soll	1	J	tvun	Rewe			8/2	5/16
Tra	ck Inspectors Si	Ignature	5	Super	Isory Ce	rtification		-	D	ata



Work Order Details (Tr)

Org ID:

MTA

Site:

LTRAIL

WO # 2545118

TEAM ONE - SECT 2: LU/CS - CM 586N TO 235N

08/25/16

CM 440, Trk 1 = Curve has a kink in both rails, gets worse in hot weather.

 Alias:
 Location:
 CHAIN_MARKER(LT Rail Chain Markers
 Status:

 Asset:
 Year:
 Manufacturer:
 Type:

 Serial Number:
 License:

 Service Address:
 1155 344 West North Ave, Baltimore MD

5.

Description

Unit of Measure

Last Reading Date

Mileage Meter:

Last Reading

CI:

CI:

Sched Start:		
Sched Finish:		
Target Start:	8/25/16	
Target Finish:	B/25/16	
Actual Start:	8/26/16	
Actual Finish:	8/26/16	
Report Date:	8/19/16	
Reported By:	MTACRON	
Requestor of Work:		

Priority:	1
Work Type:	РМ
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05- #### -05270- # ######### -0901- ####### -
	#######-000-30-00
Warranty Situation Present?	##### <u>-</u> 000-30-00

Job Plan:	2954
Job Desc:	TEAM ONE - SECT 2: LU/CS - CM 586N TO 235N
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	



Work Order Details (Tr)

Org ID:

MTA

Site:

LTRAIL

WO # 2545118

TEAM ONE - SECT 2: LU/CS - CM 586N TO 235N

08/25/16

CM 440, Trk 1 = Curve has a kink in both rails, gets worse in hot weather.

Specification			ply years with the	
Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 2: LU/CS - CM 586N TO 235N		



Work Order Details (Tr)

Org ID:

MTA

Site:

LTRAIL

WO # 2545118

TEAM ONE - SECT 2: LU/CS - CM 586N TO 235N

08/25/16

CM 440, Trk 1 = Curve has a kink in both rails, gets worse in hot weather

		Skill				Reason for	Work	Part	Contract	Regular	Premiun	Line
Task ID	Craft	Level	Labor	Component	Position	Repair	Accomplishec	Failure Warranty	Num	Hours	Hours	Cost
20 AF	REPAIR	А	RABETT			GEN	10	N	75-000-U-775	04:00	00:00	108.68
20 AF	REPAIR	R	NELSON			GEN	10	N		04:00	03:00	223.47
\.										Γotal Actu	al Labor:	332.15



Work Order Details (Tr)

Org ID:

MTA

Site:

LTRAIL

WO # 2545118

TEAM ONE - SECT 2: LU/CS - CM 586N TO 235N

08/25/16

CM 440, Trk 1 = Curve has a kink in both rails, gets worse in hot weather.

Ta	sk ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty
	10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE	· · · · · · · · · · · · · · · · · · ·					
	20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES				10			